

TÜV SÜD MIDDLE EAST L.L.C.

P.O.Box : 24240, Doha - Qatar
Tel : +974 40052000, Fax : +974 40052020
E-mail : info.q@tuvsudme.com

Head Office - P.O.Box : 45117 - Abu Dhabi - U.A.E.

Tel. : +971 2 6767600 Fax : +971 2 6762224 C.R.46452

E-mail : ad.report@tuvsudme.com

Web Site : www.tuevs-sued.de
: www.tuv-sud.ae



Middle East

Choose certainty.
Add value.

توف سود ميديل ايست ذ.م.م.

صندوق البريد ٢٤٢٤٠ الدوحة - قطر

هاتف : +٩٧٤ ٤٠٠٥٢٠٠٠ فاكس : +٩٧٤ ٤٠٠٥٢٠٢٠

المكتب الرئيسي - ص.ب: ٤٥١١٧ - أبوظبي - أ.ع.م.

هاتف : +٩٧١٢ ٦٧٦٧٦٠٠ فاكس : +٩٧١٢ ٦٧٦٢٢٢٤

رقم الرخصة : ٥٢٥١٣٢



H 89577

FITNESS CERTIFICATE

ITEM: HIGH PRESSURE INJECTION MACHINE

REPORT No.: **ZS-15Q-21459**

THIS IS TO VERIFY that the undersigned representative of this organization, did, at request of **POWER PROOF**. On the 21TH December 2015, at **DOHA**, to carry out thorough examination and functional test of the High Pressure Injection Machine.

EQUIPMENT DETAILS:

Make : CHINA
Model : IE0171
Serial No. : 1106
YEAR : 2014
Max Pressure. : 500 kg/cm²

Result of Inspection:

The above mentioned was thoroughly inspected and functionally tested with the safe operating requirements.

The unit is found to be free from any relevant defects and found SATISFACTORY in condition at the time of examination.

Witness / Inspection carried out and report issued without prejudice to the rights of whomsoever it may concern.

Inspector: ZAHER SHABAN

Stamp:

Date of Inspection: 21-12-2015
Date of Next Inspection: 20-12-2016



Authorized Signature: MUHANNAD T.DEEB
For & on Behalf of TÜV SÜD Middle East, LLC

The report is issued subject to the condition that it is understood and agreed that nothing in this report shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, expressed or implied, and TÜV SÜD Middle East, LLC shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall TÜV SÜD Middle East, LLC be liable for any injury or damage to any person, or occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only those items inspected by TÜV SÜD Middle East, LLC and which are covered by this report. TIME SHEET NO: 1016718